

HARPER COUNTY ROAD & BRIDGE
Weekly County Commission Report
October 16-20, 2017

KENT STONEBRAKER-EAST FOREMAN

1. Excavator 635 installing field entrance on Rd 682-22. Trucks 216 & 305 hauling shale to field entrance on Rd 682-22. Reset downed signs. Graders patrolling.
2. Excavator 635 clearing trees away from x-pipe on Rd 694-22. Trucks 216 & 305 hauling shale to washout around x-pipe on Rd 694-22. Truck 605 hauling half tank from the Harper County Landfill to the Anthony Yard. Trucks 216 & 305 hauling shale to Rd 751-O. Truck 605 hauling Truck 216 to the Anthony Repair Shop. Truck 305 hauling shale to Rd 704-19. Graders patrolling. Grader 255 helping with fallen tree across Rd 735-D. Dozer 627 ripping shale at the Wencil Pit. Truck 305 hauling shale to Rd 704-26.
3. Excavator 635 with Chipper 690 trimming & chipping trees in ditch along Rd 700-24. Graders patrolling. Dozer 627 ripping shale at the Wencil Pit. Fixed flat tire on Truck 216. Excavator 635 cleaning ditch along Rd 763-L.
4. Excavator 635 finishing cleaning ditch along Rd 763-L. Trucks 216 & 305 hauling sand to Rd's 761-L & 684-27. Grader 255 bringing material back up against new blacktop on Rd's 763-M & 761-V. Graders patrolling.
5. Graders patrolling. Excavator 635 cleaning ditches along Rd 763-K. Grader 255 bringing material up against shoulder of the new blacktop on Rd's 763-N & O. Broom 691 sweeping extra material off shoulder of new blacktop on Rd's 763-N & O. Trucks 216 & 305 hauling sand to Rd's 684-27 & 688-28.

JIM THOMPSON-SHOP FOREMAN

1. #155 JD 670G, service job @ 3,203 hours. #607 2006 Mack Truck, service call-leaking engine coolant.
2. Sheriff Department 2014 Dodge, checked engine codes & cleared. #190 Mower, replaced hydraulic hoses. #216 2006 Sterling Truck, service call-air leak on brakes.
3. #216 2006 Sterling Truck, replaced one rear dual air pot. EMS 2017 Ford, service job @ 15,140 miles. #607 2006 Mack Truck, service call-coolant leak. Landfill CAT Track Loader-checked over.
4. Mowed shop yard. #118 2006 Sterling Truck, checked exhaust leak & coolant.
5. #217 2006 Sterling Truck, engine repairs.

LAWRENCE SMITH-WEST FOREMAN

Sanded Rd's 714-13, 14 & 15, 745-U & V, 694-16 & 17 & 723-N. Trucks hauling gyp to fix holes on Eagle Rd's 704-13, 15, 16 & 17. Excavator 632 helping Bridge Crew dig out bulkhead & drive sheeting on Rd 711-A. Graders patrolling & spreading sand. Excavator 632 cleaning out dirt around culvert ends on Rd's 694-2 & 711-N. Excavator 632 removing & trimming up hanging tree limbs on Rd 688-2.

BRANDON HEKEL-BRIDGE FOREMAN

Started repairs to south abutment & wing walls at Bridge 711-A. Finished south abutment & wing walls & started north abutment at Bridge 711-A. Gathered materials for Culvert 682-28. Removed & replaced stringers, deck & cap at Culvert 682-28.